

## Service and Repair Pricelist



Below prices can change and are here to provide you with an estimate, please request a quote for validation

Repair Part Number	Products in Group	Euro List	GBP List	USD List
<b>Bioptic1-Repair</b>	Scanner Only, No Scale : 2122, 2200, 2321, 2421, 2422, 2431, 2751-X, 2753-X	330.00 €	£263.32	\$ 448.80
<b>Bioptic2-Repair</b>	Scanner and Scale: 2320, 2420, 275_M, 275_N, 275_P, 275_H, 275_J, 275_K	715.00 €	£570.52	\$ 972.40
<b>Bioptic-Clean</b>	Cleaning fee (Additional fee in addition to repair fee, if unit returned with insect, animal, fungal, or plant matter in device)	75.00 €	£59.84	\$ 102.00
<b>Bioptic-Diag</b>	Bioptic: labor only repairs and very low cost repairs	90.00 €	£71.81	\$ 122.40
<b>BiopticExpedite</b>	Bioptic - Three business day turnaround at repair - charge is in addition to Flate Rate Fee	150.00 €	£119.69	\$ 204.00
<b>Bioptic-Sapph</b>	Sapphire Platter adder (Additional fee in addition to repair fee if Sapphire platter needs replaced due to customer abuse)	75.00 €	£59.84	\$ 102.00
<b>DPM1-Repair</b>	6300, LXE: 8770	375.00 €	£299.22	\$ 510.00
<b>DPM2-Repair</b>	6320	430.00 €	£343.11	\$ 584.80
<b>HFScan1-Repair</b>	Hands Free: 3310g, 3580, 7120, 7180, 4980, 4800p	100.00 €	£79.79	\$ 136.00
<b>HFScan2-Repair</b>	Hands Free: 1650, 3900 ,4800dr, 4810wa, 6520,6720,7320, 7580 , 7600 Horizon, 7820 Solaris	150.00 €	£119.69	\$ 204.00
<b>HHScan1-Repair</b>	Tethered: 9590,9520,9540,5145, 3800, 3200, 3780, 4206,1200, 1250, 1300	80.00 €	£63.83	\$ 108.80
<b>HHScan2-Repair</b>	Tethered: 4600g/r, 1690, 1900g, 1900color, 1500, 1400	120.00 €	£95.75	\$ 163.20
<b>HHScan3-Repair</b>	Cordless: 1202, 1633, 1902, 3820, 4236, 4620, 4820, 5620, 9535	155.00 €	£123.68	\$ 210.80
<b>Holo-Diagnostic</b>	Labor only repairs - No Problem Found, unrepairable, firmware/OS reload	150.00 €	£119.69	\$ 204.00
<b>IK-Repair</b>	Repair for: IK8560, IK8570	340.00 €	£271.30	\$ 462.40
<b>IScan1-Repair</b>	Industrial HH: 1910i, 3800i, 4800i, 9590i	130.00 €	£103.73	\$ 176.80
<b>IScan2-Repair</b>	Industrial Cordless: 1911i, 3820i, 4820i	175.00 €	£139.64	\$ 238.00

## Service and Repair Pricelist



Below prices can change and are here to provide you with an estimate, please request a quote for validation

<b>IScan3-Repair</b>	LXE: 8510, 8520, 8750, 8760, 8900 Metrologic: 1890	235.00 €	£187.51	\$ 319.60
<b>IScan4-Repair</b>	LXE Cordless: 8810, 8820	375.00 €	£299.22	\$ 510.00
<b>LXEAcc1-Repair</b>	LXE Accessories (all not listed separately)	325.00 €	£259.33	\$ 442.00
<b>MCAcc1-Repair</b>	Single Slot bases (chargers and cradles)	125.00 €	£99.74	\$ 170.00
<b>MCAcc2-Repair</b>	Multi Slot Bases (chargers and cradles)	225.00 €	£179.53	\$ 306.00
<b>MCAcc-Diagnostic</b>	Accessories: labor only repairs and very low cost repairs	50.00 €	£39.90	\$ 68.00
<b>Mob1-Repair</b>	SL22, SL42, 6000, 60s, 5500, 5600,70e Black, ScanPal, LXE Ring Scanners: 861X, 862X, 865X	320.00 €	£255.34	\$ 435.20
<b>Mob2-Repair</b>	5700, 6100, 6110, 6500, 7600, LXE: MX8A	445.00 €	£355.08	\$ 605.20
<b>Mob3-Repair</b>	7800, 7850, 7900, 95XX, 9700, 99XX, 99EX, LXE: HX1, HX2A, HX3A, MX3R, MX3H0, MX3H2, MX5R/S, MX7R, Tecton MX7T, MX9A, VX3H	625.00 €	£498.71	\$ 850.00
<b>Mob4-Repair</b>	9900ni, 99EXni, LXE: MX7CS, TectonCS MX7L, MX9H	725.00 €	£578.50	\$ 986.00
<b>Mob5-Repair</b>	LXE : Marathon FX1	790.00 €	£630.36	\$ 1,074.40
<b>Mob-Diagnostic</b>	Mobile Computers: labor only repairs and very low cost repairs	110.00 €	£87.77	\$ 149.60
<b>MobilityExpedite</b>	Mobile computers - three business day turn around in repair - charge is in addition to Flate Rate Fee	150.00 €	£119.69	\$ 204.00
<b>OEM1-Repair</b>	Most engines are not repairable, and need to be replaced if not working	110.00 €	£87.77	\$ 149.60
<b>OEM2-Repair</b>	Most engines are not repairable, and need to be replaced if not working	190.00 €	£151.61	\$ 258.40
<b>OEM3-Repair</b>	Repair for: IS220, Tomra IS878	340.00 €	£271.30	\$ 462.40
<b>OEM-Diagnostic</b>	Labor only repairs - No Problem Found, unrepairable	50.00 €	£39.90	\$ 68.00
<b>QC800-Repair</b>	Repair for: QC800-QC850 verifier	225.00 €	£179.53	\$ 306.00
<b>QC800-Replace</b>	Corroded QC800-QC850	830.00 €	£662.29	\$ 1,128.80
<b>QC890-Battery</b>	Battery replacement only	110.00 €	£87.77	\$ 149.60

## Service and Repair Pricelist



Below prices can change and are here to provide you with an estimate, please request a quote for validation

<b>QC890-Repair</b>	Repair for: QC890 verifier	525.00 €		£418.91		\$ 714.00
<b>QCBase-Recert</b>	Recertification 1 base + 1 scanner/wand	110.00 €		£87.77		\$ 149.60
<b>QC-Diagnostic</b>	All QC products, covers: No Problem Found, Firmware/OS reload, Unrepairable	55.00 €		£43.89		\$ 74.80
<b>QCScan-Recert</b>	Additional scanner/wand tested with base certification	25.00 €		£19.95		\$ 34.00
<b>RFACC1-Repair</b>	Cordless RF single bay charge only bases: 2020-CB, COB01, 46-00358	70.00 €		£55.86		\$ 95.20
<b>RFACC2-Repair</b>	Cordless RF charging/communication bases, 4-bay battery chargers Products: 2020-5BE, MB4-BAT-SCN01, AP-0101BT-07, CCB01-010BT, MI9535-514, MI9535-538, MI9535-547, AP-010-BT	90.00 €		£71.81		\$ 122.40
<b>Scan-Diagnostic</b>	Scanners: labor only repairs and very low cost repairs	50.00 €		£39.90		\$ 68.00
<b>ScanExpedite</b>	Scanners- three business day turnaround at repair -charge is in addition to Flate Rate Fee	75.00 €		£59.84		\$ 102.00
<b>TT-Diagnostic</b>	TT & IK units, covers: No Problem Found, Firmware/OS reload, Unrepairable, Screen Protector/Stylus	90.00 €		£71.81		\$ 122.40
<b>TTExpedite</b>	TT& IK units - three business day turn around at repair - charge is in addition to Flate Rate Fee	110.00 €		£87.77		\$ 149.60
<b>TT-Repair</b>	Repair for: TT8501, TT8810	225.00 €		£179.53		\$ 306.00
<b>VM1-Repair</b>	LXE: Thor CE VM1C, VM2, VX5RAM, VX5AM, VX6, VX7, Karv VX8B, Forj VX9B, TX700, TX800	980.00 €		£781.97		\$ 1,332.80
<b>VMAcc1-Repair</b>	LXE : Thor SmartDock, Marathon Vehicle Dock	325.00 €		£259.33		\$ 442.00
<b>VX9-Battery</b>	LXE :Replace internal UPS battery in VX9	235.00 €		£187.51		\$ 319.60

Last revised 29th January 2015